


## CONTINUITY TESTING XCT FOR PDS




Before anything else, make sure your meter is set to 'Continuity'. The pictures show a few examples of what the symbol will look like. While on this setting the meter should buzz loudly when you touch both leads together.

To test the board level connections of the controller, we have to measure continuity between the red squares of each step. The multimeter should give a loud buzz/beep to confirm we have a good internal connection.



### STEP 1)



## STEP 2



## STEP 3



## STEP 4

